

# Oil Field Environmental Incident Summary

**Incident:** 20140803143523      **Date/Time of Notice:** 08/03/2014 14:35

**Responsible Party:** Real Enterprises LLP

**Well Operator:**

**Well Name:** Production water site "State of ND 1"

**Field Name:**

**Well File #:**

**Date Incident:** 8/2/2014

**Time Incident:** 03:30

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 160

**Rng:** 95

**Sec:** 20

**Qtr:** NW NW

**Location Description:** 2 miles past the gas plant north, 1000 feet down the road from the State of North Dakota production water plant on the road near 189th / about 1.5 miles East of 104th ave, in divide county.

**Submitted By:** Richard Rodgers

**Received By:**

**Contact Person:** Dave Hathaway  
PO Box 101  
Makoti, ND 58756

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 2 Mile

**Distance Nearest Water Well:** 1000 Feet

**Type of Incident:** Tank Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** Yes

**Spilled Units**

**Recovered Units**

**Followup Units**

**Oil**

**Brine**

**Other**

2

Barrels

2

Barrels

**Description of Other Released Contaminant:**

Diesel fuel spill, approximately 2 barrels.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Diesel fuel could have leached in the topsoil

**Areal Extent:**

N/A

***Potential Environmental Impacts:***

NO spill went off the road, cleaned up and fully contained to the road. Waste scraped up and disposed of, new scoria laid down on the road.

***Action Taken or Planned:***

NO spill went off the road, cleaned up and fully contained to the road. Waste scraped up and disposed of, new scoria laid down on the road.

***Wastes Disposal Location:*** Secure Marquis disposal company

***Agencies Involved:*** Local Law Enforcement Divide county

***Updates***

---

***Date:*** 8/3/2014      ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to a tank leak, remained on location according to the report. NDIC retains oversight.